

GU-1-1-CAD-Transformation - Bug #35

Update the status to INWORK for the list of model files (PRT and ASM), as well as their associated WTParts. For generic models, also set all related instances to INWORK, along with their linked WTParts.

04/30/2026 05:22 PM - Olivier Feutseu

Status:	New	Start date:	04/30/2026
Priority:	Urgent	Due date:	04/30/2026
Assignee:	Nadine Tseussu	% Done:	0%
Category:		Estimated time:	4:00 hours
Target version:		Spent time:	0:00 hour
Description			
Update the status to INWORK for the list of model files (PRT and ASM), as well as their associated WTParts.			
For generic models, also set all related instances to INWORK, along with their linked WTParts.			
When updating the status of a model, identify all related objects that must also be updated. This includes:			
Linked generic models (if applicable)			
Associated instances			
Related components (e.g., subassemblies or parts within an assembly)			
Associated WTParts			
Any other dependent or linked objects that require status synchronization			
The goal is to ensure consistency of the INWORK status across all relevant and connected items.			